

SECRET**OUT56896****SECRET 111823Z****1965 OCT 11 18 30Z****25X1**

1. CAMERA B-7 WAS USED IN MISSION 8048 FLOWN ON 8 OCTOBER 1965. PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: MANUFACTURING SPLICES ARE LOCATED IN FRAMES 314 AND 1731.

C. 9L SIDE: A SMALL PIECE OF THE EMULSION WAS LIFTED FROM FRAME 231 AND DEPOSITIED ON THE BACK OF FRAME 232. OTHER EMULSION LIFTS WERE DETECTED IN FRAMES 959, 1714, AND 2083. A SMALL EMULSION SCRATCH IS PRESENT IN THE CENTER OF THE FORMAT IN FRAME 411. A MANUFACTURING SPLICE IS LOCATED IN FRAME 1745 AND AN IMAGE OF THE SPLICE CAN BE DETECTED IN FRAME 1742.

D. BOTH SIDES: EDGE FOG, THE RESULTS OF STATIC DISCHARGES AND ROLLER CHATTER RECUR THROUGHOUT THE MISSION. THE 1L AND 2L FRAMES DO NOT APPEAR QUITE AS SHARP AS THE OTHER POSITIONS. THE FRAME COUNTER SKIPPED FROM 0001 TO 0003. THE LAST TITLED FRAME IS 2684.

E. THERE ARE NO MAJOR CAMERA OR PROCESSING ANOMALIES.

3. POSITIVES:

A. THE PI SUITABILITY IS GOOD.

B. THE PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS OBSCURE 25 PERCENT OF THE MISSION.

SECRET**-END OF MESSAGE-****SECRET****11 OCT 1965**

OPEN RECEIVED		
CV No	Office	Act.
1	File	
	CS	
	ADMIN	
	SEC DR	
	PLS	
	CEO	
	ED	
	FD	
	3	
	34	
	FD	
	FIG	
	EX-4	
	SPAD	
	RA-10	
	RA-AP	

Declassification Review by NGA/DoD